Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Improvements to Park and other works at J.P.Park in Ward No.17 RRN zone
2	Administration Approval & Date	JC/RRN/AS/2848/2013-14 Dtd.13-02-2014 by JC RRNZ
3	Technical Sanction Estimate No.& Date	CE/RRN/TS/596/13-14 dtd:22-02-2014 by CE (RRN)
4	Estimate Amount	Rs.30.00 Lakhs
5	Job Code No.	17-14-000054
6	P-Code	P -0974
7	Agreement No & date	EE/RRN/Proj/AG No./115/2013-14 Dtd.24-02-2014
8	Work order Number & Date	EE/Proj/RRN/W.O/115/2013-14 Dtd.24-02-2014
9	Contract Amount as per Agreement	Rs.3000000/- including KRIDL Charges
10	Bill Amount	Rs.2992035/- including KRIDL Charges
11	B.R. No. & Date	203/2014-15 dt.31-07-2014
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	2267/ Pages 226624 to 226633
14	Date of Inspection	15-9-2015
15	Enclosures	1) Extract of MB No.2267 Page No.226633/2 2) 5 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned person. The measurement of Items / numbers, which are susceptible for measurements have been checked and found to be Satisfactory

EE (P) RR Nagara

15/9/2015

(R.Sathyanarayana)
Inspection Report officer,